

Technical Specifications:	Bluelab pH Meter
Range:	0 – 14pH
Resolution:	0.1pH
Accuracy: (At 25°C)	± 0.1pH (at 25°C)
Temperature Compensation:	Not applicable
Operating Temperature Range:	0 - 45°C 32 - 113°F
Power Source:	2 x AAA batteries
Calibration:	Manual Calibration
Other Features:	Auto turn off, over range and under range indicators